



WARNING

Arc Flash and Shock Hazard

Appropriate PPE Required

6 in	Flash Hazard Boundary
0.19 cal/cm²	Flash Hazard at 18 in
PPE Level	Untreated Cotton
208 VAC	Shock Hazard when cover is removed
00	Glove Class
42 in	Limited Approach
Avoid Contact	Restricted Approach
	Prohibited Approach

Bus: BUS-DPB Prot: PD-DPB