



1. SEAL ALL PENETRATIONS AND JOINTS WATERTIGHT.
2. COAT INSIDE OF VAULT WITH (2) COATS OF POLYURETHANE.
3. PRECAST WALLS AND TOP. POUR IN PLACE BOTTOM.

ACID NEUTRALIZING TANK VAULT DETAIL